#### PREPARED FOR USE AT APL

#### **CLEAN ROOM AREAS**

Jon Coopersmith
Scott Lange
Rob Lee
Syed Ali

Modified for Homewood use with permission from authors



#### PURPOSE - EDUCATION

- What's important
- What to do
- What not to do
- Rational decisions
- Precautions



#### WHAT WE WILL COVER

- Basics of clean room (video)
- Practices and applications
- Discussion
- Tour and questions



#### **CLEAN ROOM USE**

- Dressing
- Entry
- Work placement
- Activity
- Discipline



#### **CONTAMINATION TYPES**

- Molecular contaminants
- Surface contaminants
- Particulate contaminants



# MOLECULAR CONTAMINANT SOURCES

- Outgassing
- Oil vapors
- Alcohols
- Paints, glues, & epoxies
- Aromatics; If you can smell it, suspect it as a contaminant

Note: Particulate filters will NOT handle molecular contaminants!



# SOURCES of SURFACE CONTAMINATION

- Finger prints
- Skin oil
- Hand cream
- Face cream
- Polish

- Oil & grease
- Face powder
- Plasticizers
- Wax



#### SOURCES of PARTICULATES

- People (skin, scales, hair, clothing lint, etc.)
- Particle shedding materials (cardboard boxes, paper)
- Abrading actions (drilling, sawing, sanding, etc.)
- Bare wood products



#### RELATIVE PARTICLE SIZES

MOST PARTICLES ARE TOO SMALL TO BE SEEN WITHOUT AID. THEIR SMALL SIZE RESULTS IN ELECTROSTATIC BONDING TO SURFACES

SIZE PARTICLE COUNTED IN CLEAN ROOMS. (0.5 MICRONS)




SMALLEST SIZE VISIBLE TO EYE. (50 MICRONS)

MEASURED
PARTICLES ARE 100
TIMES SMALLER
THAN SEEN BY THE
UNAIDED EYE



#### PARTICULATE SIZES/MATERIALS





#### PARTICLE GENERATION ACTIVITY

ACTIVITY	*PARTICLES	DESCRIPTION OF ACTIVITY
7	100,000	MOTIONLESS IN EITHER SITTING OR STANDING POSITION
	500,000	HANDS, FOREARMS, NECK AND HEAD MOTION
<b>A</b>	1,000,000	HANDS, ARMS, TRUNK, NECK, HEAD MOTION AND SOME LOWER BODY MOTION
	2,500,000	SITTING TO STANDING OR VICE VERSA
	5,000,000 7,500,000 10,000,000	WALKING AT 2.0 MPH WALKING AT 3.5 MPH WALKING AT 5.0 MPH

Copyright@JHU/APL 2000 MINIMUM 0.3 MICRON AND LARGER



# SIZE DISTRIBUTION of PARTICLES from SNEEZES or COUGHS

DIAMETER		SNEEZE	COUGH
• <1-1 uM		800,000	66,000
• 1-2 uM		686,000	21,000
• 2-4 uM		280,000	1,600
• 4-8 uM		134,000	1,290
• 8-16 uM		36,000	490
• +22 uM		4,500	85
	TOTAL	1,940,000	90,765

#### **CLEAN ROOM CLASS DEFINITION**

A CLASS (n) CLEAN ROOM IS
DEFINED AS A ROOM WITH AIR
CONTAINING NO MORE THAN (n)
PARTICLES PER CUBIC FOOT EQUAL
TO OR LARGER THAN 0.5 MICRON.

(WHERE "n" IS 100, 1,000, 10,000, ETC.)




#### CLEAN ROOM CLASSES


ISO-14644	Fed Std	209E
5	Class 100	M3.5
7	Class 10,000	M5.5
8	Class 100,000	M6.5




#### DIRT CUBE



ABOUT 6
PARTICLES PER CU.
IN. OR 10,000 PER
CU. FT.



ABOUT 58
PARTICLES PER CU.
IN. OR 100,000 PER
CU. FT.



ABOUT 165
PARTICLES PER CU.
IN. OR 300,000 PER
CU. FT.



#### **AIR FLOW**

- Air entering the room is clean
- Air leaving the room is dirty
- Air flushes dirt out of the room
- Unidirectional flow- predictable
- Position yourself out of flow



#### **BLOCKAGE**

- Blocking air flow is undesirable
- Blocking air-returns reduces flushing dirt away
- Blocking air to flight hardware increases the chance of contamination



#### **ACTIVITY**

- Limit vigorous actions
- Apply discipline to all activity
- Bring only clean items into the clean room
- Limit soldering, drilling, etc.
- Use only house or HEPA filtered vacuum
- Never sweep or dust, use C/R wet mop



#### **GARMENTS**

- Garments control contamination
  - They confine it inside or
  - They direct it to the floor
- Wear proper garments
- Wear garments properly

#### CLASS 10,000 REQUIRES

- Hoods, booties, face mask, gloves & antistatic coveralls
- Garment change once per week minimum
- Clean shoes with shoe cleaner before entering
- Entering room by walking across tacky mat
- Keep hood, if used, together with smock
- Throw away face mask & gloves on exiting
- Use approved wipes & note paper
- Pre-cleaning all tools, equipment, hardware, etc., before taking it into clean room

#### <u>RULES</u>

- No drilling, grinding, filing, sawing
- No thread cutting, deburring
- No soldering, brazing, welding
- No conformal coating or potting
- No cutting with diagonal pliers
- Do not vaporize plastic (wire insulation)
- Limit use of alcohol when cleaning
- Most glues not acceptable
- No heat stripping
- No masking, duct, adhesive tapes, only C/R tapes

#### RULES (cont)

- No wood, cardboard, regular paper
- Avoid high outgassing materials (hydrocarbons)
- No gasoline vehicles
- No unpainted wood mockups
- Use clean room note pads & paper
- No felt tip or retractable pens, only ballpoint type
- No pencils or erasers
- Use proper tools that are cleaned
- Don't touch face with gloves
- No open cell foams

#### **CLEANLINESS IS DEPENDENT**

- On YOU
- On informed and trained people
- On limiting number of people in room
- On proper garment and dress
- On no smoking, drinking, eating in them
- On limited trips in/out
- On good personal hygiene
- On not blocking air return
- On cleaning all items prior to cleanroom entry
- On frequent and thorough facility cleaning
- On clean working procedures




#### THE BOTTOM LINE

## LIMIT

### PEOPLE - ACTIVITY - MATERIAL









YOU

are the key

ELEMENT

in good

**CLEAN ROOM OPERATION** 

#### **Homewood Key Contact Information**

All emergencies security (24hrs)

x 67777

City Fire Department : Pull alarm and dial

911

Office of Safety and Environmental Health

x 68798

**Johns Hopkins Emergency Notices Web Site** 

http://webapps.jhu.edu/emergencynotices/